

CLAIM FILE INDEX

2021 Honda Ridgeline Black Edition AWD - Pavement-Marking Paint Contamination

Claimant	Domenic DiStefano	Date of Loss	August 21, 2026
Vehicle	2021 Honda Ridgeline Black Edition AWD	VIN	5FPYK3F85MB011683
Claim Status	Initial submission	Preliminary Claim	\$5,918.05

Hosted Claim Repository: Open claim repository

<https://roadsafe-claim.theitalianpalace.com/>

00 - Claim Package

Ref.	File	Purpose
00	Claim File Index.pdf	Repository map and submission inventory.
01	RoadSafe Paint Claim Form - Completed.pdf	Completed, signed and dated RoadSafe claim form; registration included.
02	Claim Presentation Letter.pdf	Claim presentation, mitigation, inspection offer and reservations.
03	Claimant Preliminary Repair Estimate and Supporting Basis.pdf	Consolidated claimant valuation; preliminary total \$5,918.05.

01 - Exhibits

Exhibit	File
A	Incident Chronology.pdf
B	Incident Location Diagram.png
C	Union Park Honda Preliminary Estimate.pdf
D	Der Glanz 2026 Repair Estimate.pdf
E	Der Glanz 2021 Ceramic Coating Invoice.pdf
F	Romik Manufacturer Correspondence.pdf
G	Romik RAL-TB Pricing.pdf
H	Firestone Tire Estimate.pdf
I	Honda 2021 Ridgeline Tire Replacement Guidance.pdf
J	Delaware Vehicle Registration - 2021 Honda Ridgeline.pdf

02 - Vehicle Damage Photographs

Damage photographs are maintained as individual full-resolution image files.

No.	File
01	Right Front Wheel Area - Overall Paint Contamination.jpg
02	Right Front Wheel Area - Heavy Paint Contamination.jpg
03	Right Front Fender Liner - Paint Contamination.jpg
04	Right Front Tire - Tread and Shoulder Paint Contamination.jpg
05	Passenger Mirror - Paint Contamination.jpg
06	Right Front Lower Body and Running Board - Paint Contamination.jpg
07	Passenger Door Handle - Paint Contamination.jpg
08	Passenger Lower Body - Fine Paint Speckling.jpg
09	Passenger Running Board - Heavy Paint Contamination.jpg
10	Passenger Running Board and Lower Trim - Paint Contamination.jpg
11	Right Rear Wheel Opening Molding - Paint Contamination.jpg
12	Right Rear Wheel Opening and Quarter Panel - Paint Contamination.jpg

03 - Security Camera Evidence

No.	File
01	2026-08-20 Pre-Incident Arrival - 16-03-37.jpg
02	2026-08-20 Pre-Incident Arrival - 16-03-38.jpg
03	2026-08-21 Departure - 11-54-44.jpg
04	2026-08-21 Post-Incident Return - 12-30-34.jpg
05	2026-08-21 Post-Incident Return - 12-30-36.jpg

Repository Organization and Use

Control	Repository practice
Single source of access	The hosted claim site is the sole evidence repository referenced in the claim presentation. All submission-facing documents, exhibits, selected damage photographs, and security-camera stills are accessible from that site.
Original-format evidence	Damage photographs are maintained as individual full-resolution image files.
Inspection and supplements	The claimant estimate is preliminary. The vehicle remains available for inspection before repair, and documented supplements may be added if repair work reveals necessary additional operations or materials.

Current Repository Structure

Folder	Contents
00 - Claim Package	Index, RoadSafe form, presentation letter, and claimant estimate.
01 - Exhibits	Exhibits A-J supporting chronology, location, repair scope, pre-loss condition, manufacturer guidance, tire valuation, and ownership.
02 - Vehicle Damage Photographs	Twelve selected full-resolution damage photographs.
03 - Security Camera Evidence	Five timestamped stills establishing pre-incident, departure, and post-incident chronology.

Prepared August 31, 2026