

EXHIBIT A

INCIDENT CHRONOLOGY

Claimant: Domenic DiStefano

Date of Loss: August 21, 2026

Vehicle: 2021 Honda Ridgeline Black Edition AWD

VIN: 5FPYK3F85MB011683

Location: Hercules Road / Newport Gap Pike (DE Route 41), New Castle County, Delaware

Date / Time	Event
August 20, 2026 - 4:03:37-4:03:38 PM	Home security-camera footage records the Ridgeline returning home. This was the vehicle's final documented arrival before the August 21 trip. The passenger/right-front tire is visible without the conspicuous white pavement-marking paint subsequently observed.
August 21, 2026 - 11:54:44 AM	Home security-camera footage records the Ridgeline leaving the claimant's residence. The purpose of the trip was to purchase gasoline at BJ's in Elsmere, Delaware.
Approximately 11:56 AM	The claimant reached the intersection of Hercules Road and Newport Gap Pike (DE 41) and stopped at the red traffic signal in the left-turn lane on Hercules Road.
Approximately 11:56 AM	While stopped, the claimant observed one or two pavement-marking vehicles traveling slowly northbound in the right-hand lane of Newport Gap Pike, moving away from the intersection. Small traffic cones were observed along the median/yellow-line area. No flaggers or personnel directing traffic were observed at the intersection.
Approximately 11:56 AM	When the traffic signal permitted, the claimant made a normal left turn from Hercules Road onto northbound Newport Gap Pike. The approximate turn path, pavement-marking vehicle positions, and cone location are depicted in Exhibit B - Incident Location Diagram .
Shortly thereafter	The claimant proceeded directly to BJ's in Elsmere without any intervening stops.
While fueling at BJ's	The claimant discovered extensive white pavement-marking paint contamination on the passenger side of the Ridgeline, including conspicuous contamination on the right-front tire and surrounding exterior areas.
Immediately thereafter	The claimant returned directly home without any intervening stops.

INCIDENT CHRONOLOGY - CONTINUED

Date / Time	Event
August 21, 2026 - 12:30:34 PM	Home security-camera footage first records the Ridgeline returning to the property. The elapsed time from the documented 11:54:44 AM departure to first visible return was approximately 35 minutes and 50 seconds .
August 21, 2026 - approximately 12:30:36 PM	Additional return footage visibly shows white pavement-marking contamination on the passenger/right-front tire that was not present in the August 20 pre-incident footage.
August 21, 2026 - after returning home	Photographs were taken documenting the contamination on the right-front tire and wheel-well area, passenger-side exterior trim and painted surfaces, passenger mirror, running board, and areas extending rearward along the passenger side.
August 21, 2026 - after returning home	A limited cleaning attempt was made using an automotive-detailing pressure washer. The pavement-marking paint did not appreciably move. No solvents, scraping, compounding, or other aggressive removal methods were used.
August 28, 2026	Larry Brown, Insurance Coverage Manager for the State of Delaware, identified RoadSafe Traffic Systems as the contractor responsible for the pavement-marking operation and directed the claimant to submit the property-damage claim directly to RoadSafe.

Evidence Note

Exact security-camera times shown above are taken from the claimant's recorded home-security system. Times identified as **approximate** are based upon the claimant's recollection and the short documented travel interval.

The incident-location diagram in **Exhibit B** is an illustrative reconstruction based upon driver recollection. Vehicle positions are approximate and the diagram is not to scale.